Easy-to-use Digital Vacuum Gauge

DISPLAY(Vacuum degree, Unitsand Battery capacity).

UNIT:Unit selection /Add value in set Mode.
SET:Long press the button into Alarm Set Mode.
SAVE/CAL:Save Alarm value /Full scale calibration/ Zero Calibration in Set Mode.



Power On/Off /Backlight.

Connection:7/16-20 UNF(1/4"Flare).

Technical Parameters



The perfect tool for HVAC technicians refrigeration maintenance

PMaximum Overload Pressure:	14 PSI/0.1 Mpa.
Range:	0~10000 Pa,0~100.00mBar,
	0~75.000 mmHg,0~75000 Micron.
Resolution:	0.01(<10Pa)、0.0001 （<10mBar）、
	0.0001 (<10mmHg)、1(<30000 Microns).
Accuracy:	2 - 100Pa: ±5%of reading (at 20℃).
Operating Temperature:	0 - 50℃(32 - 122°F).
Unit:	pa、mbar、mmhg、microns.
Refresh Rate:	0.5 Second.
Connection:	7/16 - 20 UNF(1/4"Flare).

Pro-Grade Dual Calibration

Supports full scale and zero calibration



①Full-Scale Calibration:
Press and hold "SAVE/CAL" under atmospheric pressure,the screen displays "----".

②Zero Calibration:
Press and hold "SAVE/CAL" to display "0.1Pa" when vacuum reaches 0.1Pa.



Pre-calibrated at the factory for professional-grade accuracy



APL ASIA CO., LTD. Authorized Distributor
Address: 11/129-132 Moo.5 Lamlukka Rd.,
T.Kookut, A.Lamlukka, Pathumthani 12130 Thailand.
TEL: 0-2995-4461-4
Website: www.apl-asia.com
EMAIL: sales@apl-asia.com
LINE@: @APL-ASIA